



INSTRUCTIONS

ITEM # TAC

MOUNTING

A special "goose-neck" mount is provided with your Tactical sight system. It is designed to fit onto the standard base mounts found on common and military style rifles. The top of the sight designed to hold the optic has a 6 cap screw bonnet the will wrap around the 30mm diameter portion of the sight tube. Alternative 30mm adapters for this optic may be acceptable provided they fit properly around and into the 30mm tube area.

LIGHT INTENSITY ADJUSTMENT

The intensity switch has 0-11 adjustments for brightness. The "0" position is essentially the off position. 1-11 covers various degrees of brightness 1 being the lesser and 11 the highest. Please note that for best results in targeting, the sight will best serve you at the lowest level of clear visibility. That is, if brightness is set too high, the dot does not appear to be round and a "starburst" affect appears. The highest setting is usually used only in bright daylight conditions.

ZEROING

The screw on the side, (after removing the cap), adjusts windage from right to left. The screw on top of the sight moves the dot up and down. A few shots at close range should be taken to begin with. Then move further away to fine tune the adjustments to your setting requirements. REMEMBER, THE UNIT MUST BE FITTED TIGHTLY BEFORE YOU ZERO IN AND THAT IF STORED FOR A TIME OR REMOUNTING, READJUSTING THE "ZERO" IS NEEDED.

BATTERY INSTALLATION

There is a slotted cap on the face of the dial that is numbered 0-11 for brightness adjustments of the dot. Under the slotted cap is the battery compartment. Simply take a coin and hold the compartment while turning the cap counterclockwise with the coin. This will uncover the battery. It is a commonly found 2032 size lithium battery. Please note the way the battery lies in the compartment, then remove it. Replace the old battery with a fresh one and put the cap back on. If there is no dot after you replace your battery you may have the battery in backwards.

LIMITED WARRANTY

When putting your sight into service during the zeroing in period, you should examine the sight fully and if any defects are found contact us at 800-775-3687 for return instructions and fast replacement.

For five years, if defects are found to have developed due to manufacturing or workmanship, the original purchaser may send the sight back to us for repair or replacement with the original dated sales slip and \$9.50 S&H.

For minor repairs not under warranty please return the sight with a shipping and handling charge payment of \$35. This prepayment facilitates immediate repairs and is so time-saving that often any small additional charges that may have been due can be overlooked to aid expediency. You will not be charged additional fees if more charges were due unless you are contacted first. If a repair could not be made your check and sight will be returned as received.

ALL RETURNS MUST BE FREIGHT PAID!

**ADCO SALES INC.
4 Draper Street
Woburn, MA 01801 U.S.A.**

Tel: 781-935-1799 Fax: 781-935-1011 Web: www.adcosales.com

ADCO is a registered trademark and e-dot is a trademark of ADCO Sales Inc.