

RAP4

Box Magazine Charging Instructions



1.

1. Using a phillips screwdriver, loosen the 6 screws and take off cover.



2.

2. On the motherboard, if the red wire is plugged in the top slot. You will need to unplug both wires and switch them around.



3.

2. The wires should now look like this.

WHITE- top
RED/BLACK - bottom



4.

4. Place lid back on and tighten the screws.



5.

5. Attach one or two 9V batteries to your box magazine.



6.

6. Plug in your charger and make sure the box magazine is turned to the ON position. Now, its ready to be charged.